FIG. 1




FIG. 2






FIG. 3








FIG. 5





FIG. 6






FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14





FIG. 15









FIG.17







HG 19






FIG 20


				36
	UNT			
REDUNDANCY GROUP	1	2	3	4
А	Active	Spare	No	No
В	No	Active	Spare	No
С	No	No	Active	Spare
D	Spare	No	No	Active

FIG. 21



UNIT2						
Α	В	D'				
	l	1				








FIG. 23

				$\int_{}^{36}$
REDUNDANCY GROUP	UNIT			
	1	2	3	4
А	No	Active	Spare	No
В	No	Active	Spare	No
С	No	No	Active	Spare
D	No	Spare	No	Active

FIG. 24

